

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start		Rating **	M	Issue No.	12
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD2104_01_s_2012_12				
Comment Code					
Inspector Comment					
District coordinates with adjacent district 2068 for flood fighting, but needs to have their staff flood fight trained.					

No Photos

LM Start		Rating **	A	Issue No.	14
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD2104_01_f_2012_14				
Comment Code					
Inspector Comment					
District has the O+M Manual on hand.					

No Photos

LM Start		Rating **	A	Issue No.	40
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD2104_01_s_2012_40				
Comment Code					
Inspector Comment					
District has soil and sand on site, and coordinates with adjacent district 2068 for other materials.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	0.02	Rating **	C	Issue No.	18
LM End	1.45	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.308053 °	38.295298 °
				-121.758557 °	-121.741413 °
DWR ID	DWR_RD2104_01_f_2016_18				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					

No Photos

LM Start	0.17	Rating **	M	Issue No.	20
LM End	1.72	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.306052 °	38.293465 °
				-121.757582 °	-121.737780 °
DWR ID	DWR_RD2104_01_f_2016_20				
Comment Code					
C1 : Add appropriate material and re-grade the levee to bring the crown above the design elevation.					
Inspector Comment					
Add appropriate material, re-grade and compact for proper drainage. (where needed, AND keep live stock off the crown roadway particularly during rainy weather)					

No Photos

LM Start	0.95	Rating **	M	Issue No.	28
LM End	1.41	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.298743 °	38.295683 °
				-121.748813 °	-121.741840 °
DWR ID	DWR_RD2104_01_f_2018_28				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2019_RD2104_249_28_20190311_00014.jpg



View looking downstream of vegetation on the land side slope (November 2018).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	0.95	Rating **	M	Issue No.	44
LM End	1.42	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.298715 °	38.295632 °
				-121.748818 °	-121.741767 °
DWR ID	DWR_RD2104_01_s_2019_44				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	0.99	Rating **	M	Issue No.	45
LM End	1.21	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.298293 °	38.296557 °
				-121.748402 °	-121.745178 °
DWR ID	DWR_RD2104_01_s_2019_45				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					

No Photos

LM Start	1.20	Rating **	C	Issue No.	22
LM End	1.20	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.296615 °	38.296615 °
				-121.745372 °	-121.745372 °
DWR ID	DWR_RD2104_01_f_2016_22				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Soil was added to restore waterside slope. Continue to monitor for erosion from cattle.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	1.26	Rating **	M	Issue No.	29
LM End	1.26	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.296277 °	38.296277 °
				-121.744393 °	-121.744393 °
DWR ID	DWR_RD2104_01_f_2018_29				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove down tree branches on water side slope					

Photo 1 of 1 : SP_2019_RD2104_249_29_20190311_00015.jpg



View of tree branches on the water side slope (November 2018).

LM Start	1.27	Rating **	M	Issue No.	23
LM End	1.27	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.296182 °	38.296182 °
				-121.744318 °	-121.744318 °
DWR ID	DWR_RD2104_01_f_2016_23				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Repair the slope damaged by cows and trim up the tree limbs partially blocking the erosion site.					

Photo 1 of 1 : SP_2019_RD2104_249_23_20190311_00012.jpg



Spring 2018 - Trees should be trimmed and deadwood removed, and erosion from cattle repaired.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	1.42	Rating **	A/W	Issue No.	56	
LM End	1.42	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			38.295668 °	38.295668 °	
				-121.741779 °	-121.741779 °	
DWR ID	24711					
Comment Code						
Inspector Comment						
FS_ID:24984 DS_ID:24711 EP_NO: 10185 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 09/14/2017 Permit is unavailable, missing page 3 official permit documentation. (DWR UCIP - O. Magana) FIELD_STRUCT_DESC: 16-inch steel drainage pipe through the levee, 5.7 feet below the crown. Pump in an irrigation ditch on the landside (LS). Siphon breaker on the waterside (WS) slope. (Automatic Board Order (ABO) issued as Permit No. 10185, 1964 - Erwin E. and Lucy G. Vasser, limited details available electronic permit unavailable). [Additional Reference(s): DWR Levee Log, 2006. USACE Sacramento O&M Manual 108, April 1964, (HLM 1.52), Drawing Nos. 50-04-1977 and 50-04-3379]. FS Date: 12/4/2013						

Photo 1 of 3 : UCIP_SP_2019_24984_45042.jpg



Pipe on LS slope with pump in irrigation ditch off LS toe visible in background.

LM Start	1.42	Rating **	A/W	Issue No.	56 (cont)
LM End	1.42	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_SP_2019_24984_45041.jpg



Siphon breaker on pipe at WS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	1.42	Rating **	A/W	Issue No.	56 (cont)	
LM End	1.42	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.295668 °	38.295668 °	
				-121.741779 °	-121.741779 °	
DWR ID	24711					
Comment Code						
Inspector Comment						
FS_ID:24984 DS_ID:24711 EP_NO: 10185 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 09/14/2017 Permit is unavailable, missing page 3 official permit documentation. (DWR UCIP - O. Magana) FIELD_STRUCT_DESC: 16-inch steel drainage pipe through the levee, 5.7 feet below the crown. Pump in an irrigation ditch on the landside (LS). Siphon breaker on the waterside (WS) slope. (Automatic Board Order (ABO) issued as Permit No. 10185, 1964 - Erwin E. and Lucy G. Vasser, limited details available electronic permit unavailable). [Additional Reference(s): DWR Levee Log, 2006. USACE Sacramento O&M Manual 108, April 1964, (HLM 1.52), Drawing Nos. 50-04-1977 and 50-04-3379]. FS Date: 12/4/2013						

Photo 3 of 3 : UCIP_SP_2019_24984_45040.jpg



Pump in wooden distribution box off LS toe.

LM Start	1.44	Rating **	M	Issue No.	11
LM End	1.48	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.295487 °	38.294947 °
				-121.741530 °	-121.741215 °
DWR ID	DWR_RD2104_01_f_2017_11				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : SP_2019_RD2104_249_11_20190311_00003.jpg



Remove wild growth to 20 feet from crown.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	1.54	Rating **	M	Issue No.	30
LM End	4.86	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.294170 °	38.319363 °
				-121.740883 °	-121.746788 °
DWR ID	DWR_RD2104_01_f_2018_30				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2019_RD2104_249_30_20190515_00048.jpg



View looking downstream at annual vegetation on the landside slope (Spring 2019).

LM Start	1.60	Rating **	M	Issue No.	46
LM End	4.86	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.293993 °	38.319363 °
				-121.739832 °	-121.746788 °
DWR ID	DWR_RD2104_01_s_2019_46				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2019_RD2104_249_46_20190515_00049.jpg



View looking downstream at annual vegetation on the waterside slope (Spring 2019).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	1.93	Rating **	M	Issue No.	16
LM End	1.94	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.292027 °	38.291947 °
				-121.734575 °	-121.734453 °
DWR ID	DWR_RD2104_01_s_2012_16				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					

Photo 1 of 1 : SP_2019_RD2104_249_16_20190311_00006.jpg



Scalloped bank erosion along slough is approaching levee toe.

LM Start	2.10	Rating **	U	Issue No.	47
LM End	2.39	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.292052 °	38.291605 °
				-121.731543 °	-121.726282 °
DWR ID	DWR_RD2104_01_s_2019_47				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					
Remove thick vegetation from the crown					

Photo 1 of 1 : SP_2019_RD2104_249_47_20190515_00050.jpg



View looking downstream at thick vegetation on the crown (Spring 2019).

LM Start	2.39	Rating **	M	Issue No.	13
LM End	3.19	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.291634 °	38.301552 °
				-121.726336 °	-121.730467 °
DWR ID	DWR_RD2104_01_s_2019_13				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	2.90	Rating **	A/W	Issue No.	58	
LM End	2.90	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.297380 °	38.297380 °	
				-121.730166 °	-121.730166 °	
DWR ID	24708					
Comment Code						
Inspector Comment						
FS_ID:24990 DS_ID:24708 EP_NO: 10185 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 09/14/2017 Permit is unavailable, missing page 3 official permit documentation. (DWR UCIP - O. Magana) FIELD_STRUCT_DESC: 12-inch steel drainage pipe through the levee 4 feet below the crown. Pump on pile structure in drainage canal on the landside (LS). Siphon breaker in a 12-inch steel riser on the waterside (WS) slope. (Automatic Board Order (ABO) issued as Permit No. 10185, 1964 - Erwin E. and Lucy G. Vassar, limited information available electronic version of permit missing. Replaced under Permit No. 4412, 1963 - Ervin E. and Lucy G. Vassar, limited details available electronic permit copy unavailable). [Additional Reference(s): DWR Levee Log, 2006. USACE Sacramento O&M Manual 108, April 1964, (HLM 3.12), Drawing No. 50-04-3379]. FS Date: 12/4/2013						

LM Start	2.90	Rating **	A/W	Issue No.	58 (cont)
LM End	2.90	Issue Type +	Ma	Location *	

Photo 1 of 2 : UCIP_SP_2019_24990_45047.jpg



Siphon breaker in steel riser on WS slope with pipe and flap gate visible in background at WS berm.

Photo 2 of 2 : UCIP_SP_2019_24990_45046.jpg



Pump on pier in ditch off LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	4.00	Rating **	M	Issue No.	21
LM End	4.00	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.310672 °	38.310672 °
				-121.736155 °	-121.736155 °
DWR ID	DWR_RD2104_01_f_2018_21				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : SP_2019_RD2104_249_21_20190311_00010.jpg



Repair landside slope eroded by livestock, and prevent future erosion.

LM Start	4.05	Rating **	M	Issue No.	17
LM End	4.30	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.311335 °	38.313822 °
				-121.736643 °	-121.739757 °
DWR ID	DWR_RD2104_01_s_2018_17				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 2 : SP_2019_RD2104_249_17_20190311_00007.jpg



View looking upstream at vegetation on the water side slope (November 2018).

LM Start	4.05	Rating **	M	Issue No.	17 (cont)
LM End	4.30	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2019_RD2104_249_17_20190311_00008.jpg



Waterside (right) vegetation should be managed to 20 feet from crown to allow inspection and access.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	4.25	Rating **	U	Issue No.	10
LM End	4.30	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.313253 °	38.313822 °
				-121.739152 °	-121.739757 °
DWR ID	DWR_RD2104_01_s_2018_10				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : SP_2019_RD2104_249_10_20190515_00051.jpg



View looking upstream at wildgrowth on the landside slope (Spring 2019).

LM Start	4.31	Rating **	M	Issue No.	61	
LM End	4.31	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.313955 °	38.313955 °	
				-121.739930 °	-121.739930 °	
DWR ID	24705					
Comment Code						
Inspector Comment						
FS_ID:51459 DS_ID:24705 EP_NO: 10182 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 12/06/2016 Crossing has been downgraded from "Urgent" to "Non-Urgent" no signs of leaks observed along pipe alignment (limited inspection on WS toe). According to LMA representative, this crossing was replaced 6 years ago (2010) at WS concrete apron. Recommend conducting internal inspection of pipe through the levee and LS to determine pipe integrity. (O. Magana - DWR UCIP)12/04/2013 Vegetation and soil buildup throughout pipe preventing flapgate from closing. Remove vegetation to allow gate to close properly. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 15 feet below the crown. 36-inch concrete standpipe on the landside (LS) toe. Flap gate on the waterside (WS) toe. Two corrugated metal cutoff walls installed. (24-inch pipe [HLM 4.65] authorized under Automatic Board Order (ABO) issued as Permit No. 10182, 1974 - Julia Trust Machado). [Additional Reference(s): DWR Levee Log, 2006. USACE Sacramento O&M Manual 108, April 1964, (HLM 4.65), Drawing No. 50-04-3379]. FS Date: 12/6/2016						

Photo 1 of 3 : UCIP_SP_2019_51459_45062.jpg



CMP pipe and flapgate off WS toe.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	4.31	Rating **	M	Issue No.	61 (cont)	
LM End	4.31	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			38.313955 °		38.313955 °
				-121.739930 °		-121.739930 °
DWR ID	24705					
Comment Code						
Inspector Comment						
FS_ID:51459 DS_ID:24705 EP_NO: 10182 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 12/06/2016 Crossing has been downgraded from "Urgent" to "Non-Urgent" no signs of leaks observed along pipe alignment (limited inspection on WS toe). According to LMA representative, this crossing was replaced 6 years ago (2010) at WS concrete apron. Recommend conducting internal inspection of pipe through the levee and LS to determine pipe integrity. (O. Magana - DWR UCIP)12/04/2013 Vegetation and soil buildup throughout pipe preventing flapgate from closing. Remove vegetation to allow gate to close properly. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 15 feet below the crown. 36-inch concrete standpipe on the landside (LS) toe. Flap gate on the waterside (WS) toe. Two corrugated metal cutoff walls installed. (24-inch pipe [HLM 4.65] authorized under Automatic Board Order (ABO) issued as Permit No. 10182, 1974 - Julia Trust Machado). [Additional Reference(s): DWR Levee Log, 2006. USACE Sacramento O&M Manual 108, April 1964, (HLM 4.65), Drawing No. 50-04-3379]. FS Date: 12/6/2016						

LM Start	4.31	Rating **	M	Issue No.	61 (cont)
LM End	4.31	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_SP_2019_51459_45061.jpg



36-inch concrete riser on LS toe at channel.

Photo 3 of 3 : UCIP_SP_2019_51459_45060.jpg



36-inch concrete riser with vegetation buildup inside.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	4.57	Rating **	M	Issue No.	25
LM End	4.65	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.316984 °	38.317904 °
				-121.742751 °	-121.743461 °
DWR ID	DWR_RD2104_01_s_2018_25				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

LM Start	4.71	Rating **	M	Issue No.	31
LM End	4.71	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.318407 °	38.318407 °
				-121.744495 °	-121.744495 °
DWR ID	DWR_RD2104_01_f_2018_31				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove tree limb on landside slope					

Photo 1 of 1 : SP_2019_RD2104_249_31_20190311_00016.jpg



View of down tree limb on the land side slope (November 2018).

LM Start	4.88	Rating **	M	Issue No.	19
LM End	5.51	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.319630 °	38.325042 °
				-121.747152 °	-121.754338 °
DWR ID	DWR_RD2104_01_s_2019_19				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	4.96	Rating **	U	Issue No.	24
LM End	4.96	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.320382 °	38.320382 °
				-121.748155 °	-121.748155 °
DWR ID	DWR_RD2104_01_f_2017_24				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

Photo 1 of 1 : SP_2019_RD2104_249_24_20190311_00013.jpg



Landside levee slope has slumped leaving a 2-foot vertical scarp at the shoulder. Site should be repaired.

LM Start	5.04	Rating **	M	Issue No.	41
LM End	5.04	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.321582 °	38.321582 °
				-121.748546 °	-121.748546 °
DWR ID	DWR_RD2104_01_s_2012_41				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Note and monitor the erosion site.					

No Photos

LM Start	5.07	Rating **	M	Issue No.	55
LM End	5.14	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.321883 °	38.322872 °
				-121.748527 °	-121.748700 °
DWR ID	DWR_RD2104_01_s_2013_55				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Livestock are causing erosion and slumping at landside levee shoulder. Access should be prevented. Site should be monitored.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	5.09	Rating **	U	Issue No.	65	
LM End	5.09	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.322215 °	38.322215 °	
				-121.748418 °	-121.748418 °	
DWR ID	24701					
Comment Code						
Inspector Comment						
FS_ID:53387 DS_ID:24701 EP_NO: 10182 Repair Type: Urgent Crossing Status: Found UCIP Comments: 10/12/2018 Same as last inspection; concrete headwall on WS still being undermined so crossing remains Urgent (D. Sanoski - DWR UCIP).12/06/2016 same as last inspection--pipe remains "Urgent" CMP shows holes through wall and concrete headwall is undermined. Need to contact owner. Owner will need to work with the CVFPB to comply with Title 23. (O. Magana - DWR UCIP)12/04/2013 Footing under headwall on WS toe severely undermined. Pipe rusted heavily with holes at WS and may need replacement. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 13 feet below the crown. Two cutoff walls. Concrete U-shaped headwalls on both ends. Flap gate on the waterside (WS). (24-inch pipe [HLM 5.50] authorized under Automatic Board Order (ABO) issued as Permit No. 10182, 1974 - Julia Trust Machado). [Additional Reference(s): DWR Levee Log, 2006. USACE Sacramento O&M Manual 108, April 1964, (HLM 5.5), listed as a 12-inch pipe, Drawing No. 50-04-3379, listed as an 18-inch pipe]. FS Date: 10/12/2018 5:06:00 PM						

LM Start	5.09	Rating **	U	Issue No.	65 (cont)
LM End	5.09	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_SP_2019_53387_45090.jpg



Concrete U-shaped headwall on WS toe. Note erosion scarp around headwall.

Photo 2 of 3 : UCIP_SP_2019_53387_45089.jpg



Headwall undermined on WS toe.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	5.09	Rating **	U	Issue No.	65 (cont)	
LM End	5.09	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.322215 °	38.322215 °	
				-121.748418 °	-121.748418 °	
DWR ID	24701					
Comment Code						
Inspector Comment						
FS_ID:53387 DS_ID:24701 EP_NO: 10182 Repair Type: Urgent Crossing Status: Found UCIP Comments: 10/12/2018 Same as last inspection; concrete headwall on WS still being undermined so crossing remains Urgent (D. Sanoski - DWR UCIP).12/06/2016 same as last inspection--pipe remains "Urgent" CMP shows holes through wall and concrete headwall is undermined. Need to contact owner. Owner will need to work with the CVFPB to comply with Title 23. (O. Magana - DWR UCIP)12/04/2013 Footing under headwall on WS toe severely undermined. Pipe rusted heavily with holes at WS and may need replacement. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 13 feet below the crown. Two cutoff walls. Concrete U-shaped headwalls on both ends. Flap gate on the waterside (WS). (24-inch pipe [HLM 5.50] authorized under Automatic Board Order (ABO) issued as Permit No. 10182, 1974 - Julia Trust Machado). [Additional Reference(s): DWR Levee Log, 2006. USACE Sacramento O&M Manual 108, April 1964, (HLM 5.5), listed as a 12-inch pipe, Drawing No. 50-04-3379, listed as an 18-inch pipe]. FS Date: 10/12/2018 5:06:00 PM						

Photo 3 of 3 : UCIP_SP_2019_53387_45088.jpg



Corosion through pipe with holes on WS toe.

LM Start	5.16	Rating **	M	Issue No.	39
LM End	6.84	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.323058 °	38.308411 °
				-121.748987 °	-121.758545 °
DWR ID	DWR_RD2104_01_s_2019_39				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Maintain annual vegetation on the landside slope					

Photo 1 of 1 : SP_2019_RD2104_249_39_20190515_00046.jpg



View looking downstream at annual vegetation on the landside slope (Spring 2019).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	5.22	Rating **	M	Issue No.	43
LM End	6.84	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.323340 °	38.308411 °
				-121.749973 °	-121.758545 °
DWR ID	DWR_RD2104_01_s_2019_43				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Maintain annual vegetation on the waterside slope					

Photo 1 of 2 : SP_2019_RD2104_249_43_20190515_00047.jpg



View looking downstream at annual vegetation on the waterside slope (Spring 2019).

LM Start	5.22	Rating **	M	Issue No.	43 (cont)
LM End	6.84	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2019_RD2104_249_43_20190520_00054.jpg



View looking downstream at annual vegetation on the waterside slope (Spring 2019).

LM Start	5.35	Rating **	M	Issue No.	33
LM End	5.36	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.323595 °	38.323730 °
				-121.752295 °	-121.752430 °
DWR ID	DWR_RD2104_01_s_2012_33				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 2104 Peters Pocket Tract

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough/Unit No. 02 Haas Slough	Left	6.85	05/15/2019 05/15/2019	David Julian

LM Start	5.64	Rating **	M	Issue No.	36
LM End	6.82	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Crown Surface / Depressions / Rutting		38.324625°	38.308632°	
			-121.756715°	-121.758397°	
DWR ID	DWR_RD2104_01_f_2018_36				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

*** Location**
 LS : Land Side N/A : Not Applicable
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable N : Not Inspected/Rated
 M : Minimally Acceptable C : Corrected
 U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
 Ma : Maintenance Deficiency
 Ob : Design & System Obsolescence
 En : Enforcement